PO Box 518 620 Applegate St. Philomath OR 97370 wetlabs@wetlabs.com



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

Date: 2/16/15

Customer: Univ of Hawaii/SOEST

S/N# BB2FLVMT-1016

Technician: dcm

Repairs and Modifications: Evaluated instrument and found instrument fully functional, conducted standard puck service.

Comments: New char sheets included.

PO Box 518 620 Applegate St. Philomath, OR 97370



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

10/4/07

### **Scattering Meter Calibration Sheet**

2/16/2015

Wavelength: 700

S/N BB2FLVMT-1016

Use the following equation to obtain "scaled" output values:

 $\beta(\theta_c) \text{ m}^{-1} \text{ sr}^{-1} = \text{Scale Factor x (Output - Dark Counts)}$ 

• Scale Factor for 700 nm =

3.304E-06 (m<sup>-1</sup>sr<sup>-1</sup>)/counts

Output

= meter reading counts

Dark Counts

49 counts

Instrument Resolution

1.1

counts

3.63E-06 (m<sup>-1</sup>sr<sup>-1</sup>)

#### Definitions:

• Scale Factor: Calibration scale factor,  $\beta(\theta_c)$ /counts. Refer to User's Guide for derivation.

=

- Output: Measured signal output of the scattering meter.
- Dark Counts: Signal obtained by covering detector with black tape and submersing sensor in water.

Instrument Resolution: Standard deviation of 1 minute of collected data.

PO Box 518 620 Applegate St. Philomath, OR 97370



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

### **Scattering Meter Calibration Sheet**

2/16/2015

Wavelength: 470

S/N BB2FLVMT-1016

Use the following equation to obtain "scaled" output values:

# $\beta(\theta_c) \text{ m}^{-1} \text{ sr}^{-1} = \text{Scale Factor x (Output - Dark Counts)}$

Scale Factor for 470 nm

1.324E-05 (m<sup>-1</sup>sr<sup>-1</sup>)/counts

Output

meter reading counts

Dark Counts

=

49 counts

Instrument Resolution

1.1

counts

1.42E-05 (m<sup>-1</sup>sr<sup>-1</sup>)

#### Definitions:

- Scale Factor: Calibration scale factor,  $\beta(\theta_c)$ /counts. Refer to User's Guide for derivation.
- Output: Measured signal output of the scattering meter.
- Dark Counts: Signal obtained by covering detector with black tape and submersing sensor in water.

Instrument Resolution: Standard deviation of 1 minute of collected data.

PO Box 518 620 Applegate St. Philomath, OR 97370



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

# **ECO** Chlorophyll Fluorometer Characterization Sheet

Date: 2/16/2015

S/N: BB2FLVMT-1016

Chlorophyll concentration expressed in µg/l can be derived using the equation:

CHL (µg/I) = Scale Factor \* (Output - Dark counts)

Dark counts

Scale Factor (SF)

Maximum Output

Resolution

Ambient temperature during characterization

**Digital** 

47 counts

0.0129 µg/l/count

4130 counts

1.3 counts

21.0 °C

Dark Counts: Signal output of the meter in clean water with black tape over detector.

SF: Determined using the following equation:  $SF = x \div (output - dark counts)$ , where x is the concentration of the solution used during instrument characterization. SF is used to derive instrument output concentration from the raw signal output of the fluorometer.

Maximum Output: Maximum signal output the fluorometer is capable of.

Resolution: Standard deviation of 1 minute of collected data.

The relationship between fluorescence and chlorophyll-a concentrations in-situ is highly variable. The scale factor listed on this document was determined using a mono-culture of phytoplankton (Thalassiosira weissflogii). The population was assumed to be reasonably healthy and the concentration was determined by using the absorption method. To accurately determine chlorophyll concentration using a fluorometer, you must perform secondary measurements on the populations of interest. This is typically done using extraction-based measurement techniques on discrete samples. For additional information on determining chlorophyll concentration see "Standard Methods for the Examination of Water and Wastewater" part 10200 H, published jointly by the American Public Health Association, American Water Works Association, and the Water Environment Federation.



# **Instrument Checklist**

Date: 2/17/2015	S/N:	BB2FLVMT-1016	Order #	26016	
Contents:					

Description	Qty	Packed	
■ ECO Meter	11	X	
■ Calibration/Characterization Sheet	1	X	
■ Repair/Modification Sheet	1	X	
Dummy Plug			
■ Lock Collar			
■ Anti-Static Shipping Bag	1	X	
■ Hard Plastic Protective End Cap	1	X	
■ Pigtail with Lock Collar			
■ Spare Parts Card			
■ Dummy Plug Switch			
■ Compact Disc	1	X	
■ Test Cable			
■ ECO to SBE Patch Cable			
■ White Saddle			

Checked by:	СМН		
Comments:		37	